ILLINOIS ENVIRONMENTAL PROTECTION AGENCY **BOL/FOS SPRINGFIELD REGION**

MEMORANDUM

DATE:

October 17, 2012

TO:


DLPC/Division File

FROM:

David C. Jansen, BOL/FOS Springfield Region

SUBJECT:

FOS File



US EPA RECORDS CENTER REGION 5

On September 25, 2012 I stopped at the Nutronics facility at 1701/1703 Peoria Road in Springfield to document that the multiple connected brick buildings formerly used by Nutronics were being demolished. These buildings had been demolished after their purchase from Albert and Sharon Darran by the State of Illinois Dept. of Transportation (see attached current property record for 1701 Peoria Road obtained from http://tax.co.sangamon.il.us/SangamonCountyWeb/app/homeAction.action)

I arrived at about 2:30 p.m., and observed a Halverson Construction Co., Inc. track hoe loading general construction or demolition debris into a Flowers Sanitation roll off box (see attached photos # 001 and 002). Earlier in the day I had seen a Flowers Sanitation truck loaded with debris leaving this site and headed toward the Sangamon Valley Landfill. Scrap metal removed from the buildings had been segregated from other debris and placed into a separate roll off box for recycling. An IL DOT worker and a licensed asbestos inspector worker were present monitoring the demolition. Suspect asbestos containing debris had also been segregated onto the ground for special handling prior to disposal.

IL DOT also purchased two other nearby properties adjacent to Peoria Road and had the buildings located there demolished also (see attached aerial photo for locations).

I returned to the former Nutronics facility on October 11, 2012, arriving at about 11:30 a.m. I noted that all the multiple connected buildings that were part of the Nutronics facility were gone, the basement was filled in, and the resulting vacant lot had been hydro-seeded with a green colored mixture of mulch and seed (see attached photos # 001 and 002). Some workers were finishing up the repair of the sidewalk that ran parallel to Peoria Road east of the Nutronics facility.

ec:

USEPA, Fred Micke

cc:

BOL/FOS - Springfield Region

LPC

Division of Land Pollution Control

DIGITAL PHOTOGRAPHS



Date: 09/25/12
Time: 2:31 p.m.
Direction: NE
Photo by: D. C. Jansen
Exposure #: 001
Comments: Halverson
Construction Co., Inc. track
hoe loading demolition
debris from former
Nutronics, Inc. buildings
into Flowers Sanitation roll
off box



Date: 09/25/12
Time: 2:31 p.m.
Direction: N
Photo by: D. C. Jansen
Exposure #: 002
Comments: Halverson
Construction Co., Inc. track
hoe loading demolition
debris from former
Nutronics, Inc. buildings
into Flowers Sanitation roll
off box

File Names: 1671200054~09252012-[Exp. #].jpg

Page 1 of 1

1671200054~09252012.doc

LPC

DIGITAL PHOTOGRAPHS



Date: 10/11/12 Time: 11:34 a.m. **Direction: NE**

Photo by: D. C. Jansen

Exposure #: 001

Comments: vacant lot that has been hydro-seeded at former location of Nutronics, Inc. buildings.

A work crew was repairing the sidewalk that ran along the east edge of the former buildings parallel to Peoria Road.



Date: 10/11/12 Time: 11:35 a.m. **Direction: SE**

Photo by: D. C. Jansen

Exposure #: 002

Comments: vacant lot that has been hydro-seeded at former location of Nutronics, Inc. buildings.

1671200054~10112012.doc

File Names: 1671200054~10112012-[Exp. #].jpg

Page 1 of 1

LPC # 1671200054 — Sangamon County Springfield/Nutronics FOS File



